



Contract Managers Searching for Inspection Issues

SEARCHING FOR EXISTING ISSUES

Step 1
Select customer and site from the drop-down menu


Step 2
Select Existing Issues

Search by Plot

Search by Inspection number or date of inspection

Search by Issue Category

Search by Date Range



Search by Staff Responsible

Search by Status, default All Statuses

Note
Awaiting Review is the contract managers responsibility
Awaiting Staff Resolution is the scaffolder responsibility



Contact Us:
Office Telephone 01295 367 117

Email
sales@allsafescaffolding.com

Allsafe Scaffolding Ltd
Target House
Thorpe Way Industrial Estate
Banbury, Oxfordshire, OX16 4SP



Raising standards in scaffolding