


Raising standards in scaffolding



Scaffolders Closing Issues created from Inspections



SCAFFOLDER RESOLVING INSPECTION ISSUES



SCAFFOLDER RESOLVING INSPECTION ISSUES



Scaffolder to resolve issue, select camera icon and take a picture as proof of the issue being resolved


The picture icon will turn green




Details of the issue with any notes that the contracts manager has written with a picture of the issues if one has been taken

Step 4

Select Mark Resolved







Raising standards in scaffolding

www.allsafescaffolding.com



Contact Us: Office Telephone **01295 367 117**

Email sales@allsafescaffolding.com

Allsafe Scaffolding Ltd Target House, Thorpe Way Industrial Estate Banbury, Oxfordshire, OX16 4SP